DATE 1811Z 26 MAR 63	SOCIETY S
70 * DIRECTOR)QC
ACTION: OSA (1-2-3-4-5-6-7-8-9-10)	PRIORITY
INFO : S/C (11) TOR: 1825Z 26 MAR 63	IN 70224
TO PRITY METO	CITE 8789
INSTALLATION WOULD TAKE TWO TO THREE DAYS WOO OFF AWAITING COMBINING VOR WORK WITH OTHER WESUCH A STANDOWN MORE PRODUCTIVE. 2. MUST POINT OUT THAT INSTALLATION VOR SOLVE ALL WEATHER PROBLEMS. IT WILL MATERIAL CASES WHERE HIGH OVERCAST IS PROBLEM. SOME DUE EXCESSIVE TURBULENCE ALOFT THAT, IN THIS PROGRAM, PRESENT PROBLEMS. ALSO, LOW CEILING WINDS WITH ATTENDANT VISIBILITY AND CROSSWING WEATHER PROBLEMS THAT VOR WILL NOT NECESSARIANT PARTICULARLY TRUE OF 121 WHICH HAS NO INSTRUMENTATION. 3. AWARE OF DESIRABILITY OF VOR AND	ORK THAT WOULD MAKE NOT NECESSARILY LLY AID IN THOSE WEATHER CANCELLATIONS PHASE OF IGS AND HIGH SURFACE IDS PRESENT ILY OVERCOME. JMENT FLIGHT CAPABILITY
INSOFAR AS PRACTICABLE, ITS INSTALLATION.	
APPROVED FOR RELEASE DATE: AUG 2007 REPRODUCTION BY OTHER THAN THE ISSUING OFFICE	EXCEP I Exclarized from automatic devangedian and dedastication IS PROHIBITED. Copy No.